


## Solenoid Wiring Diagram (front view)



1. Battery Cables, positive and negative, are the only connections necessary. Use #6 wire.
2. Coat all terminals with anti-corrosive lubricant or similar protective coatings.
3. Solenoid mounting bracket is grounded. Ground terminals may be connected on either or both sides.